
Putting on (Donning) PPE





Perform Hand Hygiene Include fingertips, rub thumbs in rotation and wrists



Put on gown; tie at neck & waist




Surgical Mask



Integrated Mask/visor



Fit-tested N95 Respirator
Perform seal check by
cupping hands around edges
and exhale to identify any
air leaks.



Place face shield over face

Step (2) Choose your mask

Surgical masks and integrated mask/visor are appropriate for all indications requiring droplet contact precautions except COVID-19. Fit-tested N95 respirators are now required when caring for patients suspected for or confirmed with COVID-19 (see below)

 Secure straps/ties at the middle of the head and neck, mold clip to your nose and face.

Fit-tested N95 respirators are used in the following scenarios:

- when caring for patients on airborne or airborne + droplet contact precautions
- when caring for patients suspected for or confirmed with COVID-19.
- when there is risk of exposure to aerosolized excretions/secretions (e.g. AGMP)
- See Poster 74368 for steps to 'Putting on fit-tested N95 respirator'



Put on gloves to cover wrists of gown